## Class X

S. No.	Year	No. of Registered Students	Pass Percentage	Remarks
1.	2019	122	100	-
2.	2020	106	100	-
3.	2021	117	100	-

## Class XII

S. No.	Year	No. of Registered Students	Pass Percentage	Remarks
1.	2019	51	100	-
2.	2020	41	100	-
3.	2021	33	100	-

## **Physical Infrastructure**

## Area of Campus (In Sq.Mtrs)

Total area of campus – 20234

Build up area (Sq.mtrs) – 7269

Area of Playground (Sq.Mtrs) – 3664

#### Number of classrooms(Principal Block) & Size in Sq.mtrs

## Number of classrooms (Administrator Block) & Size in Sq.Mtrs

Classrooms - 5 Size - 38x62
Computer Lab - 1 Size - 64x120
Physics Lab - 1 Size - 38x62

# Youtube video link of School Infrastructure

https://youtu.be/O\_xUsQKNre0

#### New Building

GF = 40.20 x 28.00 x 3.70

FF = 40.20 x 28.00 x 3.70

Total Area: 1125.6 x2 = 2251 m2

#### Old Building

 $GF = 98.08 \times 15.90 \times 3.70$ 

FF = 98.08 x 15.90 x 3.70

SF= 98.08 x 15.90 x 3.70

Total Area: 1559.47 x 3 = 4678.41 m<sup>2</sup>

Both together: 7269 m<sup>2</sup>

## Play ground area

New Building to Temple Wall = 88m

Central Gate to Main Entry old Building = 35.40m

88 x 35.40 = 3155m<sup>2</sup>

Children's Park area = 10.80 x 20.10 = 217m<sup>2</sup>

East entrance area = 11.55 x 25.30 = 292m<sup>2</sup>

Total area = 3155 + 217 + 292 = 3664m<sup>2</sup>

#### FITNESS CERTIFICATE FOR SCHOOL BUILDING FOR THE YEAR 2019-20

	11111200 02111111011121		
1.	Name of Officer	: Renjn . S. Francis Assi Engineer : Assissi Vidyani Kethar Public school	
2.	Name of School	: Assissi Vidyani Kethar	n
3.	Location with name of Educational		
	District/Sub-District.	: Njarakkal, Ernakwan Vypin	7
4.	Classification of building and size.	: Permanent RCC Buildin	ng
-	classification of ballaning and size.	O OF- 1× 98-08×18-90×3-70(	Rec B
		@ F.F. 1×98.08×15.90 ×3.70 (RCC	Blog
		3) SF - 1×98.08×15.90×3.70 (Tra	iss roof
		New Building	
		1) Co.F-1×40.20×22.60×3.70m(	RCC
		@ F.F-1×40.20×28.60×3.70mc	
5.	Period for which the certificate is issued	: 2019-2020	Bldg)
6.	Nature of defects if any		
	(i) Foundation and Basement	: Rec Foundation	
	(ii) Super Structure	: RCC Framed Super Struct	cture
	(iii) Doors and Windows	: Cheru Teak	
	(iv) Wood work wrought & put up		
	(iv) Kind of Roof with short specification	: Rec, Aluminium shee	et
	(v) Flooring	: cement plastered	
	(vi) Whether regular maintenance		
	Attended to or not.	:	
7.	Any major defects modified which will make	the	
	Building unsafe in any manner	:	
8.	Whether maintenance works have been don	ne properly : Yes	
9.	Whether structure is sound or not for condu	cting classes: Sound under Weather Condition	norma
	ed that the school was inspected by me on		
condu	ct class for the period up to 31 March 2020 fo	r the reason stated above	
Place:	Njarakkal	Down -	

Assistant Engineer
Local Self Government Department Section
Narakkal Grama Panchayath
PIN - 682 505

Date:

### CAPITAL ONE TRADING

16/326, PALOOPARAMBIL, BLDG, OPP.BPCL KOCHI REFINERY MAIN GATE AMBALAMUGHAL

ERNAKULAM -682302 MOB: 7591919939, EMAIL: capitalonekochi@gmail.com

Date: 08/01-2022

#### TO WHOMSOEVER IT MAY CONCERN

This is to certify that we have serviced and refilled all first aid fire equipment at **Assisi Vidyaniketan Public School**, Perumpilly, Njarakkal, Ernakulam District, Kerala – 682505.All equipment are currently rated as valid and functional till 07/01/2023.

The building and premises are found to be free of risk from fire hazards and eligible for functioning as a school.

This certificate is issued only for renewal of affiliation with the Central Board of secondary Education – Delhi.

WITH BEST REGARDS

#### CAPITAL ONE TRADING BRANCH

16/326, Palooparambil Bldg Opp. BPCL Kochi Refinery Main Gate, Ambalamugal Ernakulam - 682 302 GST IN: 32DGGPK 9249Q1ZN

